



:Avalon N4-14S 07430 WARNING 2015/2/3 13:22, 000601

From: avalon@cspresonline.com

To: avalonerror@cspresonline.com, michael@cspresonline.com

Date: 2/3/2015 12:26 PM

WARNING 2015/2/3 13:22, 000601

Either the conveyer, processor, or stacker is not turned on or is in the busy status or is in the error status.

:Avalon N4-14S 07430 ERROR 2015/2/3 14:05, 00E115

From: avalon@cspresonline.com

To: avalonerror@cspresonline.com, michael@cspresonline.com, AgfaTechMPalmer@aol.com

Date: 2/3/2015 1:10 PM

ERROR 2015/2/3 14:05, 00E115

Plate size is incorrect

Plate size (in the Y direction) is longer than the set value.

:Avalon N4-14S 07430 ERROR 2015/2/3 15:26, 00130E

From: avalon@cspresonline.com

To: avalonerror@cspresonline.com, michael@cspresonline.com, AgfaTechMPalmer@aol.com

Date: 2/3/2015 2:30 PM

ERROR 2015/2/3 15:26, 00130E

Auto-loader error

During the removing a paper, PH90 does not switch to ON.

:Avalon N4-14S 07430 ERROR 2015/2/3 13:08, 005157

From: avalon@cspresonline.com

To: avalonerror@cspresonline.com, michael@cspresonline.com, AgfaTechMPalmer@aol.com

Date: 2/3/2015 12:13 PM

ERROR 2015/2/3 13:08, 005157

Plate size is incorrect

The size check program of the cetering function detects that the measured plate size is shorter than expected one.

:Avalon N4-14S 07430 ERROR 2015/2/3 13:20, 00514F, Init

From: avalon@cspresonline.com

To: avalonerror@cspresonline.com, michael@cspresonline.com, AgfaTechMPalmer@aol.com

Date: 2/3/2015 12:24 PM

ERROR 2015/2/3 13:20, 00514F, Init

Remove plate in transport unit

A plate exists on the discharge table in the transport unit during initialization.

:Avalon N4-14S 07430 ERROR 2015/2/2 16:39, 00130E

From: avalon@cspresonline.com

To: avalonerror@cspresonline.com, michael@cspresonline.com, AgfaTechMPalmer@aol.com

Date: 2/2/2015 3:44 PM

ERROR 2015/2/2 16:39, 00130E

Auto-loader error

During the removing a paper, PH90 does not switch to ON.