

Baking Aluminium Alloys AA3103/1050

The baked plates will revert to their nominal size on cooling. More important is controlling the optimum temperature for correct baking of the image areas, should this be exceeded the *Tensile Strength* of the metal is destroyed.

Baking time for these Alloys are 5- 10 minutes at $\pm 250^{\circ}\text{C}$, one means of checking the oven temperature by not just relying on the Oven's Temperature Gauge is attaching a *Temperature Sensitive Film Gauge* to a waste plate and check.

Regards, Alois