

Goss Community Press

Hello AMCGuy,

Due to the flawed dampening system on Goss Community Presses and a Manager resistant to change, your options are limited.

Even if you implement some of the suggestions it will always be a - *High Maintenance task* with this type dampening system.

- 1) If possible remove Molleton covered dampeners by using Bare Back Rollers or cover suitable rollers using 3M Dampener roller sleeves, these shrink fit onto the roller.
- 2) If you stay with Molleton rollers have them washed via Dampener Washing Machine – NOT by hand.
- 3) Revert back to using a Chilled Dampening Fluid Circulation system also use Acid type fountain solution concentrate.
- 4) Run Mourning Bars outside of the web width area.

Regards, Alois

PS - Just do it! Cut “V”s --into the water stops and allow some water to flow, I don’t want to see SOLID areas of “Catch Up”

