

Problem: - Set-off from retarded ink drying on uncoated side of C1S paper.

- 1) Have you used this C1S substrate manufacturer before?
- 2) Have you tried C1S substrate from a different manufacturer? - Even printing 500/1.000 sheets during the print run and seeing the results.
- 3) Re – non U.S. Printing plants, do they use the same C1S substrate from the same manufacturer as you?
- 4) pH of F.S?
- 5) pH of C1S substrate, Coated/Uncoated sides?

And the word is - Chalking