

Type	Equipment	Voltage	Fuse
SM 52-1	Press with 50/60 Hz	200 – 240 V	40 A
		350 – 480 V	25 A
		600 V	16A
	Press with inking unit temperature control with 50/60 Hz	200 – 240 V	50 A
		350 – 415 V	32 A
		440 – 600 V	25 A
SM 52-2 (-P)	Press with 50/60 Hz	200 – 240 V	63 A
		350 – 400 V	40 A
		415 – 480 V	32 A
		600 V	25 A
	Press with inking unit temperature control with 50/60 Hz	200 – 240 V	80 A
		350 – 380 V	50 A
		400 – 480 V	40 A
		600 V	32 A
SM 52-4 (-P)	Press with 50/60 Hz	200 – 220 V	125 A
		230 – 240 V	100 A
		350 V	80 A
		380 – 440 V	63 A
		480 V	50 A
		600 V	40 A
	Press with inking unit temperature control with 50/60 Hz	200 – 240 V	125 A
		350 – 380 V	80 A
		400 – 480 V	63 A
		600 V	50 A
SM 52-6 (-P)	Press with 50/60 Hz	200 – 220 V	125 A
		350 – 380 V	80 A
		400 – 480 V	63 A
		600 V	50 A
	Press with 50/60 Hz	200 – 220 V	160 A
		230 – 240 V	125 A
		350 – 440 V	80 A
		480 V	63 A
		600 V	50 A